

BOARD MEETING DATE: 10/15/2024

ITEM NO: Xd

RECOMMEND THAT the District Board of Trustees approves the Annual Comprehensive Safety Inspection Report.

THIS RECOMMENDATION is to document the Board's review and approval of the safety inspection.

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2012 & F.A.C. 69A-58
FISCAL YEAR 2024-2025

College Facility: North Florida College Fire District: Madison
SCHOOL / FACILITY: Main Campus
ADDRESS: 325 Turner Davis Drive, Madison, FL 32340

OF SERIOUS FIRE SAFETY VIOLATIONS 0
OF NON-SERIOUS FIRE SAFETY VIOLATIONS 0

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION) _____ September 13, 2024
CONTRACTED COMM. COLLEGE BOARD FIRESAFETY INSPECTOR NAME PRINTED _____ INSPECTION DATE

FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION) _____
Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993
INSPECTOR ADDRESS & PHONE NUMBER _____

SIGNATURE DATE _____ 9/13/2024 _____
FIRE INSPECTOR SIGNATURE / DATE _____
FIRE INSPECTOR CERTIFICATION NUMBER _____ 133209
FIRE INSPECTOR CERTIFICATION NUMBER _____

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency is in an area without an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavilion, etc.

North Florida College has met the requirements of F.S.S. 1013.12(2)(d): X YES ___ NO

Approval of Reports by Board (Including Letter) ___ YES ___ NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

Glenn Strickland
FACILITY ADMINISTRATOR NAME PRINTED
Physical Plant Director
FACILITY ADMINISTRATOR TITLE

Glenn Strickland
FACILITY ADMINISTRATOR SIGNATURE
9-16-2024
SIGNATURE DATE

ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2012 & F.A.C. 69A-58
FISCAL YEAR 2024-2025

College Facility: North Florida College Fire District: Madison # OF SERIOUS FIRE SAFETY VIOLATIONS 0
SCHOOL / FACILITY: Perry Center # OF NON-SERIOUS FIRE SAFETY VIOLATIONS 0
ADDRESS: 319 North Byron Butler Parkway, Perry FL 32347

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION) _____
FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION) _____
SIGNATURE DATE _____
CONTRACTED COMM. COLLEGE BOARD FIRE SAFETY INSPECTOR NAME PRINTED Jeb W. Bynum (Municipal Fire Safety Inspector) September 11, 2024
INSPECTION DATE
FIRE INSPECTOR CERTIFICATION NUMBER _____
FIRE INSPECTOR CERTIFICATION NUMBER 133209
INSPECTOR ADDRESS & PHONE NUMBER Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993
COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE [Signature] 9/13/2024

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency is in an area without an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavilion, etc.

North Florida College has met the requirements of F.S.S. 1013.12(2)(d): X YES ___ NO

Approval of Reports by Board (Including Letter) ___ YES ___ NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

Glenn Strickland
FACILITY ADMINISTRATOR NAME PRINTED
Physical Plant Director
FACILITY ADMINISTRATOR TITLE

Glenn Strickland
FACILITY ADMINISTRATOR SIGNATURE
9-16-2024
SIGNATURE DATE